

State of Utah

Department of **Natural Resources**

MICHAEL R. STYLER Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA Division Director JON M. HUNTSMAN, JR. Governor

GARY R. HERBERT Lieutenant Governor

Representatives Present During the Inspection:					
Company	Mark Reynolds				
OGM	Karl Houskeeper Environmental Scientist III				

Inspection Report

Permit Number:	C0070011
Inspection Type:	PARTIAL
Inspection Date:	Wednesday, March 14, 2007
Start Date/Time:	3/14/2007 8:30:00 AM
End Date/Time:	3/14/2007 11:00:00 AM
Last Inspection:	Tuesday, February 13, 2007

Inspector: Karl Houskeeper, Environmental Scientist III

Weather: Partly Cloudy, Temp. 50 Deg. F.

InspectionID Report Number: 1238

Accepted by: pgrubaug 91

3/22/2007

Permitee: HIAWATHA COAL CO INC Operator: HIAWATHA COAL CO INC Site: HIAWATHA MINE COMPLEX

Address: PO BOX 1245, HUNTINGTON UT 84528

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Cı	urr	en	t	A	cr	e	a	9	es

Total Permitted	12,177.00
Total Disturbed	290.00
Phase I	
Phase II	
Phase III	

Mineral Ownership

Types of Operations ✓ Federal ✓ Underground ✓ State Surface County ☐ Loadout Processing Fee Other Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

There are no amendments pending.

Citation #10004 was terminated on 02/15/2007, because the mine ID sign was installed.

Inspector's Signature:

Date

Wednesday, March 14, 2007

Karl Houskeeper, Environmental Scientist III

Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

1594 West North Temple, Suite 1210, PO Box 145801, Salt Lake City, UT 84114-5801 telephone (801) 538-5340 • facsimile (801) 359-3940 • TTY (801) 538-7458 • www.ogm.utah.gov Permit Number: C0070011 Inspection Type: PARTIAL

Inspection Date: Wednesday, March 14, 2007

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
- b. For PARTIAL inspections check only the elements evaluated.
 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcemen
1.	Permits, Change, Transfer, Renewal, Sale	✓		✓	
2.	Signs and Markers	V		✓	
3.	Topsoil				
4.a	Hydrologic Balance: Diversions	V			
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	~			
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring	✓		✓	
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments	V		✓	
8.	Noncoal Waste				
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.a	Roads: Construction, Maintenance, Surfacing				
16.b	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Inspection Continuation Sheet

Permit Number: C0070011 Inspection Type: PARTIAL

Inspection Date: Wednesday, March 14, 2007

Page 3 of 3

1. Permits, Change, Transfer, Renewal, Sale

There are no amendments pending.

2. Signs and Markers

Both mine ID signs were in place at the point of public access to the permit area. The signs contained the required information.

4.d Hydrologic Balance: Water Monitoring

Fourth quarter 2006 water monitoring information is in the EDI website, but has not been uploaded. Water monitoring is current.

7. Coal Mine Waste, Refuse Piles, Impoundments

The refuse pile appeared stable with no visible hazards.